

TROUBLE-SHOOTING







TROUBLE-SHOOTING



























8. EXCESSIVE CO2 CONSUMPTION (canister runs out before producing around 100lt of sparkling water /600g) ORING (R-UG) OR TEFLON GASKET (R-RIC) MISSING / DAMAGED CARBONATOR "T" ORING DAMAGED CO2 INLET ORING (IF PRESENT) DAMAGED

